

No. 9


## Complete each Hydrabolt installation before drilling next hole

Safety  
First

Don't drill all the holes first and then install all the Hydrabolts, it is dangerous.



Always drill the hole, insert **and pressurise** each Hydrabolt before moving to the next position.



**Hydrabolt**<sup>™</sup>  
Knowing you're safe at the face

ISO 9001:2008  
International accreditation

**New Concept Mining**

New Concept Mining (Pty) Ltd  
PO Box 125000, Alrode 1451  
109 Adcock Ingram Avenue, Aeroton, South Africa  
Fax 011 494 1060  
Tel 011 494 6000  
www.ncm.co.za

